Delaware County Infiltration & Inflow Reduction

CSEAO ANNUAL SUMMER CONFERENCE

JUNE 17, 2025




OUTLINE

- Delaware County Collection System Intro
- CMOM Data Collection
- Scioto Hills SSES and Rehab
 - Flow Monitoring Tactics
- Highmeadows SSES and Rehab
- Northstar Rehab


DELAWARE COUNTY REGIONAL SEWER DISTRICT

- Established 1969
- 9 treatment plants
 - 10 MGD Alum Creek WRF
 - 6 MGD Olentangy Environmental Control Center (OECC)
- 32 pump stations
- 37.7 miles of force mains
- 547 miles of gravity sewer
- Serve >60% of the Delaware County population



DCRSD I&I ISSUES

- I&I contributed to only 17% of SSO/WIB events 2009-2024
- I&I impacts some pump station
 & treatment plant operations
- Proactive I&I reduction



HOW WERE I&I REDUCTION AREAS SELECTED?

History of I&I impacts:

- Scioto Hills WRF
- Northstar WRF
- Leatherlips Pump Station
- OECC facilities plan recommended future EQ

OECC areas identified from flow monitoring:

- Highmeadows
- The Retreat

DATA COLLECTION

- In-house data collection & studies
 - CCTV
 - Manhole Screening
 - Flow Monitoring
- Collections Dept began CCTV in 2004
 - Currently 2 CCTV trucks
 - 17.2 miles inspected in 2024
 - Granite / GraniteXP / GraniteNet since 2011





CCTV INSPECTION FINDINGS


- 2020 overall review of CCTV data
- Concrete, truss, and clay (common before 1989) had the most frequent infiltration defects

•	Pipe Material	Concrete	Truss	Clay	DIP	PVC
	Length Inspected (ft) 2017-2020	16,819	73,731	10,875	6,385	598,212
	No. of Infiltration Defects per 1000 LF	1.4	1.0	<mark>0.6</mark>	0.2	0.1


PIPE TYPES & SIZES




- 8" to 48" Diameter
- Oldest sewers installed in 1974



SEWER BLOCKAGES (DEPOSITS, GREASE, RAGS) HAVE DECLINED SINCE CCTV





2022 CCTV PRIORITY BY SEWER AGE



MANHOLE SCREENING

- Mobile app developed in house
- Collections, Inspectors, & Operator of Record
- Manholes screened since 2022 = 3,508 (27%)






⊕ Zoom to

FLOW MONITORING

- 10 temporary flow meters
- 3 Rain Gauges
 - 2 Ohio EMA
 - 1 DCRSD




FLOW MONITORING ANALYSIS FINDS HIGH I&I AREAS

Median
Rainfall% (R) in
Sanitary Sewer

<3%

>3 - 6%

>6 - 11.8%




FLOW MONITORING ANALYSIS FINDS HIGH I&I AREAS

Average Wet-Weather Peaking Factor

<3

>3 - 6

>6 - 9.2



FLOW
MONITORING
ANALYSIS
FINDS HIGH
I&I AREAS

Average Wet-Weather

Peaking Factor


<3

>3 - 6

>6 - 9.2

— Truss


— Clay



SCIOTO HILLS

- 156-home subdivision
- Scioto Hills WRF constructed in 1974
- Design flow = 84,000 gpd
- Collection system installed in 3 phases: 1974 & 1978 (truss pipe), & 1989 (PVC)
- 2012 Alternatives to address overflows at treatment plant:
 - Convert to pump station OR
 - Sanitary Sewer Evaluation Study (SSES)





2011-2013 SCIOTO HILLS SSES

- Flow Monitoring
 - Dec 2011 Aug 2013 (21 months)
 - Before, during, and after rehab
- Mainline CCTV
- Manhole inspections
- Smoke testing
 - One direct connection removed by homeowner
 - Also found 2 houses without roof vents the smoke went in the house!
- No private property inspection or testing Owners are responsible for entire service line beginning at branch joint of the wye

2012 SCIOTO HILLS CCTV



Leaking Joint




Leaking Stub




Leaking Wye

2012 SCIOTO HILLS POINT REPAIRS



Scioto Hills WRF Average Monthly Flow




2021
POINT
REPAIR
CONDITION
AFTER 9
YEARS














FLOW MONITORING TACTICS


• #1 TIP: Compare meters to meters, not to storms.











Scioto Hills vs OECC Average Monthly Flow

















SCIOTO HILLS 2021 CCTV RESULTS










• CIPP Lining 6,300 LF (41%) of 8" pipe



- 42 full-wrap lateral liners with 5' extension
- 3 taps not restored
- 5 open-cut tap repairs
- Only defective taps were lined/repaired (47 of 69)
 - Break-in/hole
 - Infiltration
 - Encrusted deposits
 - Joint offset/ separated
 - Protruding



- DCRSD Rules & Regulations: owners are responsible for O&M of entire service line beginning at the branch joint of the wye or tap connection
- Notices sent to owners of defective taps with two options:
 - Agree to County's repair & remain responsible for service line OR
 - Decline repair & be responsible for hiring contractor & cost of repair
- 100% Agreed

- Design complete: July 2023
- Bid opening: Sept 2023
 - 5 bids received
 - Lowest & Best: \$573,384
- Contract allowed 365 days to substantial completion
- CIPP lining began Nov 2024
- 13 weeks to complete all but 4 taps




- LESSONS LEARNED:
- Require notice before cleaning & inspection
- I&I migrated between liner and host pipe to two taps that were not lined
 - Consider lining ALL taps




2024/12/06


SCIOTO HILLS WRF AVERAGE MONTHLY FLOW




Scioto Hills WRF vs Tartan Fields WRF Effluent Flow



Scioto Hills WRF vs Tartan Fields WRF Effluent Flow





Scioto Hills WRF vs Tartan Fields WRF Effluent Flow





HIGHMEADOWS


- 1980s residential subdivision and commercial / light industrial
- 43% truss or clay pipe
- 2015-2017 flow monitoring
 - Avg peaking factor = 1.7
 - Median % of rainfall volume in sewer (R value), Nov-May = 5.4%
- I&I volume impacting future EQ at OECC
























2022 HIGHMEADOWS VILLAGE SEWER REHAB PROJECT

- Delaware County's 1st sewer lining project
- 2,890 LF cured-in-place pipe (CIPP)
- Geopolymer lining of manholes
 - 2 in Highmeadows
 - 7 in Alum Creek service area











NORTHSTAR

- 304 homes & a golf course
- Oldest sewers 2009
- PVC and ductile iron pipe
- 3x flow per equivalent residential unit (ERU) in two years!
- Impacting effluent pond








HOW MANY GALLONS PER DAY?

A. 8,000 gpd

B. 24,000 gpd


C. 76,000 gpd






GUSHER #2 AT NORTHSTAR








GUSHER #3 AT NORTHSTAR











WRINKLE IN 25' OF FULL-LENGTH LINER



LEAKS AROUND OVERLAP IN PARTIAL LINERS



2ND FULL-LENGTH CIPP POST-LINING



DCRSD MISSION STATEMENT

"To deliver regulatory-compliant, reliable, and affordable services for the citizens of Delaware County"

